Inspection Report

By Sri. Muniyappa .G .M
Retd. Executive Engineer

Name of Work:- Drilling of Borewells providing pump motor & servicing at Model Colony, Ward No. 15, Dasarahalli Sub Division (Near Maruthi Temple)

B.R. No.: 327/14-15 Date: 16-07-2014

Estimated Cost: Rs. 7.00 Lakhs

Bill Amount: Rs. 7,69,674/-

Date of Inspection: 17-06-15

Observation & Conclusion:

The above said Work Drilling of Bore Wells providing pump Motor and Servicing at Model Colony, Ward 15 Dasarahalli has been shown by the Concerned AE.

The above said Work has been inspected along with the Concerned AE.

The Water Supply to the Residents Area of the Vicinity of the Bore well is running Smoothly

The Records pertaining to Bore well and KEB has been Verified in regard to installation of pump and Motor

The Energy Meter has been fixed and the RR no 1119.

— 2 —

The Work done is Satisfactory.

The Measurements have been Verified and OK is found Satisfactory.

17/08/18

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ವಲಯ-ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬೆಂಗಳೂರು

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike.
Dasarahalli Zone, Bangalore-57.

Name of Work:- Drilling of Borewells providing pump motor & servicing at Model Colony, Ward No. 15, Dasarahalli Sub Division (Near Maruthi Temple)

Borewell R.R. No. : DWP-1117

B.R. No.: 327/14-15 Date: 16-07-2014



Verified

G.M.MUNIYAPPA
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶ್ರೀ ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬೆಮಂಪಾ
ಬೆಂಗಳೂರು

Name of Work:- Drilling of Borewells providing pump motor & servicing at Model Colony, Ward No. 15, Dasarahalli Sub Division. (Near Maruthi Temple)

Borewell R.R. No. : DWP-1117

B.R. No.: 327/14-15 Date: 16-07-2014

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)